




Let s make an
Ethernet (Cat.5) Cable

Straight Wiring? Cross Wiring?



What should we prepare?


- Materials
 - Raw UTP Cable
 - RJ-45 Connectors




- Tools
 - Cutter Knife
 - Nipper
 - Pressing Tool





1. Curve out the UTP Coating





Untwist the center cores




3.1. Straight Wiring




3.2. Cross Wiring



4. Flatten the center cores by hand
and cut the edge with nipper



5. Insert the cable to RJ-45 connector



6. Press the connector

